JOHN ASHCROFT

Governor

Director



Division of Energy
Division of Environmental Quality
Division of Geology and Land Survey
Division of Management Services
Division of Parks, Recreation,
and Historic Preservation

## STATE OF MISSOURI DEPARTMENT OF NATURAL RESOURCES

#### DIVISION OF ENVIRONMENTAL QUALITY

Springfield Regional Office 1155 East Cherokee Street Springfield, MO 65807 417-883-4033

### MEMORANDUM

DATE: January 24, 1989

TO: Greene County General

FROM: Charles L. Kroeger

SUBJECT: Moses Electric - Boonville & Commercial

On January 21, 1989, I noted that most of the trashy material has been cleaned up behind the Moses Electric property at Boonville and Commercial in Springfield.

The pallets had been stacked up and cardboard and paper trash removed. The oil contaminated gravel was still at the site but the amount is small enough that it is not felt to be a serious health or environment concern.

CLK/ps

cc: Randy Lyman, Sanitary Services

201 E. Commercion

DEC 1 2 1988

Division of Energy

Division of Environmental Quality

Division of Geology and Land Survey Division of Management Services

Division of Parks, Recreation,

and Historic Preservation

JOHN ASHCROFT Governor

#### FREDERICK A. BRUNNER

Director



#### STATE OF MISSOURI

#### DEPARTMENT OF NATURAL RESOURCES

#### DIVISION OF ENVIRONMENTAL QUALITY

Springfield Regional Office 1155 East Cherokee Street Springfield, MO 65807 417-883-4033

Hazardous Waste/ General Greene County

November 16, 1988

Mr. Matt Hembry Moses Electric Company 1010 N. Clay Springfield, MO 65806

Dear Mr. Hembry:

This office recently received a call from the Springfield Sanitary Services Department regarding your failure to cleanup the spilled transformer oil behind building at the corner of Commercial and Boonville Streets in Springfield, Missouri. We had kept them advised of our involvement in the matter and they are concerned because of the need to repair the manhole cover behind the building.

On December 6, 1988, I drove past the site and noted that there had apparently been no removal of contaminated material since we spoke on November 21, 1988 when you indicated you would get someone to cleanup the site the following day.

I again express our concern regarding the failure to remove all of the contaminated material because of the presence of PCB's in the oil with which the material was contaminated and the possibility of exposure to the contaminants.

Your prompt attention to this matter will be expected and appreciated. If you have any questions, feel free to contact me.

Sincerely,

SPRINGFIELD REGIONAL OFFICE

Charles L. Kroeger

Environmental Specialist

cc Springfield Sanitary Services
Mr. Art Groner, Enforcement Section,
Waste Management Program, Jefferson City, Missouri

201 E. Commercial

#### JOHN ASHCROFT Governor

#### FREDERICK A. BRUNNER

Director



Division of Energy
Division of Environmental Quality
Division of Geology and Land Survey
Division of Management Services
Division of Parks, Recreation,
and Historic Preservation

### STATE OF MISSOURI

#### DEPARTMENT OF NATURAL RESOURCES

#### DIVISION OF ENVIRONMENTAL QUALITY

Springfield Regional Office 1155 East Cherokee Street Springfield, MO 65807 417-883-4033



Hazardous Waste/ General Greene County

October 26, 1988

Mr. Bill Moses Moses Electric Company 1010 N. Clay Springfield, MO 65806

Dear Mr. Moses:

Please find enclosed the copy of our September 28, 1988 letter to you regarding the cleanup of the spill of transformer oil behind your building at the corner of Boonville and Commercial Streets in Springfield, Missouri.

A review of files discloses that we have not yet received word from you regarding the cleanup. You were to advise us of the progress in removing the remaining contaminated soil and material by October 5, 1988.

Please inform us of your progress in this matter within ten days of the date of this letter.

Your cooperation in this matter will be expected and appreciated.

Sincerely,

SPRINGFIELD REGIONAL OFFICE

Charles L. Kroeger

Environmental Specialist

cc Mr. J. Randall Lyman, Springfield Sanitary Services

201 E. Commencia

## JOHN ASHCROFT Governor

#### FREDERICK A. BRUNNER

Director



SEP 3 0 1988

Division of Energy
Division of Environmental Quality
Division of Geology and Land Survey
Division of Management Services
Division of Parks, Recreation,
and Historic Preservation

#### · STATE OF MISSOURI

#### DEPARTMENT OF NATURAL RESOURCES

#### DIVISION OF ENVIRONMENTAL QUALITY

Springfield Regional Office 1155 East Cherokee Street Springfield, MO 65807 417-883-4033

#### **MEMORANDUM**

DATE:

September 19, 1988

TO:

Greene County General Haz Waste

FROM:

Charles L. Kroeger

SUBJECT: Spill at Boonville and Commercial Streets

The SRO was contacted by the Springfield Sanitary Services Department regarding an oil spill that occurred behind the old fire station at the intersection of Commercial and Boonville Streets in Springfield. The building had recently been sold to Moses Electric.

There had been five transformers stored behind the building after they were removed from the Kentwood Arms building by a Killian Construction Company subcontractor. Apparently a Mr. Lawrence Tureaud of 818 N. Franklin in Springfield dumped the oil out of the transformers and began hauling them to his residence to recover the copper from them. The oil was dumped onto the ground and flowed into a sanitary sewer drain.

Ken Teeter of the LSP was contacted and proceeded to the site. He had the oil tested for PCB's by the city Public Works Department and found the oil to be less than 50 ppm. He then met with Mr. Hambry, manager at Moses Electric. Mr. Hambry agreed that Moses Electric would have the oil contaminated soil removed and properly disposed of. Because the oil was not contaminated with PCB's, it was agreed that it could go to the sanitary landfill rather than a hazardous waste landfill.

Mr. Hambry indicated on September 15, that they had a contractor who would be removing the soil on that date. He estimated that there would be less than a truck load and that there was no free liquids in the soil. Although Suzanne Ranard could not be contacted for approval in disposing of the waste without first obtaining a written special waste disposal permit, Ken indicated that he understood that the LSP had a working agreement with Suzanne which allowed them to give approval for oil contaminated waste from a spill to go to the landfill without generating a lot of paperwork as long as the spill was minor and resulted in less than a truck load of waste. This was passed by Tom Greddel who agreed that the soil could go to the landfill without the usual paperwork.

201 E. Commercial

I confirmed this with Mr. Henry Cole of the city and he agreed to allow the soil to go to the landfill if I agreed to write a follow up letter indicating the Department's position.

Cleanup of the site was to be completed on September 15, 1988, and the site was inspected on September 20, 1988. At that time it was noted that there was a substantial amount of oil contaminated material left at the site. This included paper material as well as pallets and other trash. There was also still some oil soaked gravel alongside the building. It appeared that clean up was performed with a front end loader with little effort to remove all of the visibly contaminated material. A letter was written to Moses Electric advising them of the need to do additional removal.

Respectfully Submitted

Charles LA

Charles L. Kroeger

Environmental Specialist Springfield Regional Office ALCED @ 2:50 p.m.

913-236 3888

JOHN ASHCROFT

FREDERICK A. BRUNNER
Director



Division gy
Division of Env. al Quality
Division of Geolo<sub>b</sub>, Land Survey
Division of Management Services
Division of Parks, Recreation,
and Historic Preservation

#### Kenneth R. Teeter

Environmental Emergency Specialist Laboratory Services Program

MISSOURI DEPARTMENT OF NATURAL RESOURCES
Division of Environmental Quality
P.O. Box 176 Jefferson City, MO 65102
314-751-7929 Emergency Response 314-634-2436

# DISPAT-HER COLLINS 31-1040

BATALLION CHIEF HAPPIS

201 E. Commencial (OLD # 2)

LANDREACE TUREAUD-

1 100 KUW TRANSFORMEN N 50 gals. 4 N 75 KW 11 5. N/20 gals.

4 03 5 Labelled KON PCB" 170 gald

Nayle 5 th, 5 too?

0-50 PPM - CU TEST KIT TOOK LIQUID SIMPLE IN 40M VIAL.

TUREAND WAS TOLD TO DUMP OIL AT REAR OF OLD \$ 2, (201 E.

Commencial) DOWN DRAIN AND CONLD HAVE FOR SCRAPS TOOK 2 TRANSPORMED TO HOME ONN. FRANKLIN. Area sealed off and TARCTOR impounted AT SITE, D.NR. E.R.

CALLED IN JEFF City.

BACKHOE - MAN - NO NAME

Moses Exercic? MayBE
Someone told them they could have
them, if they damped will out.

Col Mien-Roul Estate Mondo
201E. Commoncion

CITY NEGOTIATING WITH MOSES ELECTRIC. LISA Ran - NOTGODORS SOND they SAN Moses acreic union Transisancés. 3 on site 1 of Z ON FRANKLIN

#### City of Springfield Water Pollution Control Section Pollution Complaint/Report Form

	Tucton Comptaint/Re	eport Form Date_	9-6-88
Report From:    Citizen   Fire Dept   Sewer Maintenance   Other	Receive	ed By: LYMAN ed To: f Incident: 9-9	+ CORSON
Complainant Information Name *Seringfield Vic Address 203 W. Commo Phone 831-6387 Directions(if needed) * Rev. Kevin Gleas	EACIBL Address Phone	sible Party Infor AWRENCE TUR 8 818 N. F. 863- 6810	EAUD
Possible contamination  Other Pertinent Informa  VIA DRAIN. CONFIRM	surface water	what body?	
DYE TEST PERIFORME	D 9-1-88.		
Who to contact:  □DNR 417-883-4033  ☑DNR 314-634-2436  ☑EPA 913-236-3378 □Fire Dept 864-1719 □Police Dept 864-1719	☐ Bob Schaefer ☐ CU 831-8320 ☐ Street Dept ☑ Health Dept ☐ Sewer Maint	☐ Sewer Const ☐ Chemtrec 800 ☐ DOT ☐ NRC 312-790-5 ☑ Other ⑤ o 6 T	5500 U RNER
Details of Incident: M. APPARENTLY DUMPED TRAM. SANITARY SEWER AT RE ESTIMATED 170 GALS. SANITARY). 3 TRANSFOR	SFORMER OIL ON GRO TAR OF 201 E. COM (10 % OF WHICH U MERS STILL ON SITE	UND AND DOWN D MERCIAL (MOSES UAS SPICLED ON CR , 2 HAD BEEN 7	RMERS AND  ORAIN TO  EZECTRIC?)  OUND, 90% to  RANSFERLED
N. FRANKLIN LABRIED" N. SCREENING TEST WHICH I. REDOLTED TO LARRY ALDO BOS TURNER AND INFORM ACTION NEEDED: KEN TEETER ARRIVED	ON-PCB", SHN W, VOICHTOD O-50 PPM CERSON, DNR AND BRUED PROPERTY ON WHICE AT 4:36 P.M 91	THERSPOON OF C. U. ON A PUDDIE OF OIL CLE MORRISON, ET H SPILL OCH PRED I	RAN A PCB L. SPILL WAS PA. CALLED 'S BURLINGTON R. TO MR TER SAMPLED
POOL OF OIL AND SP SAMPLE TO DOAN BY NUON 9/8/88. OFFER LIABLE PARTY PCB LEVEL OF CONCE	With onspood OF C. Mr. TEETER IND. To Clear up Spil	CATED IF "NON F	ANALYSIS CB" WILL ENSE, IF

### Investigation Results

61-11-	-												
9/6/88-			14204	16/	ERM	7-10-	WTD		0 14	DUEL	)E_	FFFE	
016 51	oicu	DE7	ECTE	0						<u>.</u> .			
9/8/88 -	Bicc	DEA	L- FE	3.Z.	AGEN	17 C	ALLEZ	258	82-	3303	3)	mo	00
TO INUE	STICA	75	SPILL	RE	5PONS	BLE	PAR	TIE	5.				
		-=											
			777777	177.0		ini Too		1 1		7777	- 0	F (1, %)	
		9.9							4 6				
· <b></b>					77			V. 5 2 2 3		7.7.7		7555	
		essection was under	umay kasan ngga Marian Sila									5.*5 Fall (100 and 100 and 1	6/01 391
			<del></del>										
							.2						
A 11 - 101 - 111	101	- 12	5,1-11	7	74.5	4 4 h L 1	114.40	73-147-1	ALCOH.	-			
							~~~~	CV36 m	- Po				
												7	
							74.						
100		1016											
	enene.	Ter Sandaria											
Single Service	- Sec. 3-1 2-3		9111110	2 24		:111	2 JA M	. July 1			. On Carries and	e selve sesses	20022200
Day.	F BBB V	2450	5,55		77 5 2		sa Restro-2.5	4.00			7.7	1000	
				C 15 Ca 5 Ca					Ver. 11				
									<u> </u>				
	A CONTRACTOR				Fr 51 25 9		14.75 P. 14.	) , ?		5		700 83	
		112146		7,54	· C () ()		TVE CO	SERVER.	To The Co			26.5 10	
			14	*27.59	V 3 (A 3		7.50 22.6		777-7	1997 15			-
· · ·								V 2 7V		20 92			
	19	40 1					100 100	10 -	10,000	130			1.
		10.016	2 4. 5.		1 13 34 1		AGE LANCE	PERE CO.	500 -	125		5 555	
	;;						<u> </u>	really.					
								100 150	200	11.04			
	- P. 4.					4	- T	41 C		1. 14.	.711	· - \	
775572		-565-			7		<del>-</del> -						
	ore to							an d					
												- ·	
						J = 3	3 N. J.		. vç		1.		-
C1 44 7 9 1								9.10					
V 144								C					



# CITY UTILITIES of SPRINGFIELD

301 E. Central • P.O. Box 551 • Springfield, Missouri 65801 • (417) 831-8311

September 8, 1988

Memo To: Bob Corson

Water Pollution Control Inspector

Sanitary Services City of Springfield

Subject: PCB Analysis

SAMPLE ID

LAB NO.

PCB CONCENTRATION (PPM)

DNR Sample

388-0460

< 1

No. 88-0614 9/7/88 16:30

Collector- KT

Sample received: 09/08/88 Sample analyzed: 09/08/88 Sample reported: 09/08/88

Analyst: RJG

John T. Witherspoon, Ph.D. Director - Laboratories

Operations

/jtw

201E. Commencial

# CITY OF SPRINGFIELD WATER POLLUTION CONTROL MONITORING AND ANALYSES REPORT

SAMPLE NUMBER: 88-06/4 TIME SAMPLER IN: 16:43: SAMPLE NAME: 18 Aus former O- TIME SAMPLER OUT:								
DATE OF SAMPLE: 9-7-88 METER START:								
DATE SUBMITTED: 9/		METER END:	And the same transport of the same and the s					
TIME SUBMITTED:	1	TEMP. DE	EG/C:					
SAMPLE TYPE: GRAD SUBMITTED BY:		_DIS. OXY.	MG/L:					
SET UP BY:	08	FLOW:						
SET UP BY: Ken Teet REMOVED BY: Ken Te	0.700							
		(No. 9) 1105 1 105 1 105 1 105 1						
COMMENTS: 201 E.		- TRANSFOI	RMIER Oil	Spi-1/				
CONVENTIONAL	I METALS	ANALYSES	OTHER					
PARAMETERS	11	DISLVIRECOV		3				
BOD-5 MG/L:			VOLATILE OF	RGANICS				
PH STD. UNITS:	.ICRI		BASE NEUTRA	ALS				
NFR MG/L:	1.ZN11		ACID EXTRAC	TIBLES				
	ICDII		PESTICIDES_					
TOC MG/L: NH3-N MG/L: .	· INT		T. C. D. D.					
NO3-N MG/L:			ASBESTOS					
NO2-N MG/L:		i	TOTAL P.P.					
NO3+NO2-N MG/L:	1110		T.C.L.P.					
CHLORIDE MG/L:			P.C.B.	77				
SULFATE MG/L:		1						
TKN MG/L:								
0-P04-P MG/L:								
O-PO4-P D MG/L:		1						
TP MG/L:		11						
CN TOTAL UG/L:		1						
CN AMENBL MG/L:		!!						
TDS MG/L:PHENOLICS UG/L:		!						
	IBE I							
	ITL							
TURBIDITY NTUS:	IK							
CONDCT UMOS/CM:	INA I	''						
TOT COLI/100ML:								
FEC COLI/100ML:	1 3 2 2 3 3 4 4			. — — — — — — — — — — —				
FEC STRP/100ML:	11							
CHAIN OF CUSTODY RECORD								
RELINQUISHED BY	RECEI	VED BY	DATE I	-TIME				
Kan al Do	+ 21		10/01					
fluith of jeeles	1. 11 10 1	aron	17/7/201	17111				
SEALED [] SHIPPED []	SEALED []		1/88	11.45				
Bal D	! ( h=+	6.	1011					
SEALED [] SHIPPED []	I SEALED []	Cu	19/8/88	08:10				
SEALED [] SHIPPED []	SEALED []	201 E (	Onnan	. 0				

ANAL 1 DET 3 METH 7 7 FILE 103

RUN 1 PCB SCAN

SENSITIVITIES 250 6

8 49 0-24 BUN 13 1.52

11.17

13.75 BHD

ANAL 1 DET 3 METH 7 7 FILE 103

RUN 1 PCB SCAN 7: 23.5 9 / 8 / 88

SENSITIVITIES 250 6

TIME	AREA BC:	RRT	RF	C NAME
1.18	2.3750 T	0.118	1.000	29.5533 !
1.52	5.3606	0.152	1.000	66.7040
11.17	0.2726 V	1.117	1.000	3.3930 ! E. Commencent

```
ANAL
                        7 7 FILE 101
     1
        DET
               3
                  METH
RUN
        2 PCB SCAN
SENSITIVITIES
               250
                    1260 (50ppn)
                 259.39.37
                                                                or. 60
                            2.53
                              - Z.93
                             3.37
                      3.81
                    4.29
                           5.06
                5.89
              6.55
         7.14
         7.70
           8.81
                     11.16
       12.88
       13.59
      BND
INAL 1 DET
              3
                 METH
                         7
                                7 FILE 101
        2 PCB SCAN 7 : 56.1
                              9 / 8 / 88
SENSITIVITIES 250 6
  TIME
            AREA
                 BC RRT
                                RF.
                                            C
                                                HAME
                              1.000
           2.4352 T
                      0.118
                                         1.7884 !
  1.18
```

0.138 1.000

1.000

1.000

200

0.162

0.183

1.38

1.62

1.83

2.3678 T

3.3891 T

4.2416 T

1.7389 !

2.4889 !

3.1149 !

20/ E. Comme

# CITY OF SPRING LD WATER POLLUTION CUNTROL MONITORING AND ANALYSES REPORT

SAMPLE NUMBER: 88-06/4  SAMPLE NAME: TRAUS FORMER O. TIME SAMPLER OUT:  DATE OF SAMPLE: 9-7-88  METER START:  DATE SUBMITTED: 17/7/88  METER END:  TIME SUBMITTED: 1 TEMP. DEG/C:  SAMPLE TYPE: GRAD DIS. 0XY. MG/L:  SUBMITTED BY: FLOW:  SET UP BY: Ken Teefer VOLUME:  REMOVED BY: Ken Teefer DEPTH:  COMMENTS: 20/ E. Commercial - Transformer O:/ Spill								
CONVENTION	JAI	METOL	S ANALYS					
	RAMETERS	I I TOTA	ALIDISLVI	RECOVI	OTHER PARAMETERS	3		
BOD-5	MG/L:				UNI OTTLE OF	RGANICS		
PH STD. L	JNITS:	ICR			BASE NEUTRA	ALS		
NFR	MG/L:	I.ZNI			ACID EXTRA	CTIBLES		
COD	MG/L:	ICDI			PESTICIDES			
TOC	MG/L:	PB			T. C. D. D.			
NH3-N	MG/L:	NI			ASBESTOS			
	MG/L:	HG	!!		TOTAL P.P.			
NOS+NOS-N	MG/L:	HG			I. C. R. T			
CHLORIDE	MG/L:	MN			P.A. R			
SULFATE	MG/L:	BA			1.00.			
TKN	110/6 =							
0-P04-P	MG/L:	ASI	1 1					
0 FU4-F D	11076	IHL1						
TP	MO/L:	58	1					
	UG/L:	B	!1	1				
	110/ [ ]	LU						
	MG/L:		!!	!				
	MG/L:							
MBAS	MG/L:	TL I	1 1					
TURBIDITY	NTUS:	K I	-1 1	1				
CONDCT UMO	S/CM:	NA I	_1					
IUI CULI/I	OOML:	1		1				
LEC COCIVI	OOML:			1				
FEC STRP/1	OOML:		11	1				
CHAIN OF CUSTODY RECORD  RELINQUISHED BY RECEIVED BY DATE TIME								
7/	5				!!			
SEALED []	SHIPPED []	I SEALED D	( -	n	9/7/88	17:45		
SEALED []	SHIPPED []	SEALED C	then	en-	9/8/88	08:10		
SEALED []	SHIPPED []	   SEALED [	]		1			